		ROUTING			
TO:	NAME AND ADDRESS		[	DATE	INITIALS
1					
2					
3					
4					
TΤ	ACTION	DIRECT REPLY		PREPA	RE REPLY
	APPROVAL	DISPATCH			IMENDATION
	COMMENT	FILE		RETUR	N
	CONCURRENCE	INFORMATION		SIGNA	TURE
REM	ARKS:				
	FROM: NAME	, ADDRESS, AND PHO	ONE N	Ο.	DATE

SECRET		72		
(	Security Classification)			
	NOFORN			
(See inside cover)				
CONTROL NO.	Z-15357/83			
	NPIC/PEG (10/83)			
COPY	OF			

25X1

Warning Notice
Intelligence Sources or Methods Involved
NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

SECRET
(Security Classification)

Warning Notice
Intelligence Sources or Methods Involved
(WNINTEL) or (D)

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

## **DISSEMINATION CONTROL ABBREVIATIONS**

NOFORN-

Not Releasable to Foreign Nationals

NOCONTRACT-

Not Releasable to Contractors or

Contractor/Consultants

PROPIN-

Caution-Proprietary Information Involved

ORCON-

Dissemination and Extraction of Information

Controlled by Originator

REL...

This Information has been Authorized for

Release to . . .



(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER  Pagel _ of _l _		•	SECF	RET		2
Page 1 of 1  Copy Attachment to Z-15357/83  NPIC/PEG (10/83)  LAUNCH PAD DISMANTLEMENT TYURATAM SPACE LAUNCH SITE A1, USSR  1. SIGNIFICANCE: A SIGNIFICANT PORTION OF THE LAUNCH PAD SUPERSTRUCTURE HAS BEEN REMOVED FROM THE PAD. (SWN)  2. REMARKS: THE UMBILICAL TOWER AND THE LAUNCH VEHICLE STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCH PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NECESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E		/a\	TIONAL BUOTOCE ABUIL			
LAUNCH PAD DISMANTLEMENT TYURATAM SPACE LAUNCH SITE A1, USSR  1. SIGNIFICANCE: A SIGNIFICANT PORTION OF THE LAUNCH PAD SUPERSTRUCTURE HAS BEEN REMOVED FROM THE PAD. (SWN)  2. REMARKS: THE UMBILICAL TOWER AND THE LAUNCH VEHICLE STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCH PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NECESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E		(c) NA	TIONAL PHOTOGRAPHIC			
LAUNCH PAD DISMANTLEMENT TYURATAM SPACE LAUNCH SITE A1, USSR  1. SIGNIFICANCE: A SIGNIFICANT PORTION OF THE LAUNCH PAD SUPERSTRUCTURE HAS BEEN REMOVED FROM THE PAD. (SWN)  2. REMARKS: THE UMBILICAL TOWER AND THE LAUNCH VEHICLE STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCH PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NECESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E				Attachment to	Z-15357/83 NPIC/PEG (10/83)	
1. SIGNIFICANCE: A SIGNIFICANT PORTION OF THE LAUNCH PAD SUPERSTRUCTURE HAS BEEN REMOVED FROM THE PAD. (SWN)  2. REMARKS: THE UMBILICAL TOWER AND THE LAUNCH VEHICLE STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCH PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NFCESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E		Сору				
SUPERSTRUCTURE HAS BEEN REMOVED FROM THE PAD. (SWN)  2. REMARKS: THE UMBILICAL TOWER AND THE LAUNCH VEHICLE STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCE PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NECESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E		T				2
STABILIZATION ARMS HAVE BEEN REMOVED FROM THE LAUNCH PAD. THE LAUNCH PAD APERTURE RING AND THE TWO LARGE SERVICE ARMS REMAIN IN PLACE; HOWEVER, THEIR REMOVAL AND REPLACEMENT PROBABLY ALSO WILL BE NECESSARY. THIS MAJOR REPAIR ACTIVITY CLOSELY PARALLELS THE 1979-80 PAD REFURBISHMENT WHICH TOOK APPROXIMATELY 15 MONTHS TO COMPLETE. (SWN)  3. COORDINATES 45-55-12N 063-20-33E	1.				AD	
	2.	STABILIZATION LAUNCH PAD APP IN PLACE; HOWE WILL BE NECESS PARALLELS THE	ARMS HAVE BEEN REI ERTURE RING AND THI EVER, THEIR REMOVAL SARY. THIS MAJOR I 1979-80 PAD REFURI	MOVED FROM THE LAUNCH E TWO LARGE SERVICE A L AND REPLACEMENT PRO REPAIR ACTIVITY CLOSE BISHMENT WHICH TOOK	RMS REMAIN BABLY ALSO	
	3.		COORDINATES 45-5	5-12N 063-20-33E		2
			1			2

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

WARNING NOTICE Intelligence Sources and Methods Involved

**SECRET**